



wires & fabriks
An ISO 9001:2000 Company





Tensiometer


**MATERIAL TESTING
EQUIPMENT FOR
MEASURING TENSION
OF FORMING FABRIC
DRYER SCREEN &
WOVEN BELTS**

Specifications


1.	Tension range on dial:	0.0 N to 200 N/Cm																								
2.	Operating tension range:	0.5 N to 160 N/Cm																								
3.	Accuracy: Note---10.0 N/Cm =5.58 PLI	<table> <tbody> <tr> <td>In the range</td> <td>0.5 to 10 N</td> <td>:</td> <td>1.0 N/Cm</td> </tr> <tr> <td>In the range</td> <td>10.0 to 100.0 N</td> <td>:</td> <td>5.0 N/Cm</td> </tr> <tr> <td>In the range</td> <td>100.0 to 160.0 N</td> <td>:</td> <td>10.0 N/Cm</td> </tr> </tbody> </table>	In the range	0.5 to 10 N	:	1.0 N/Cm	In the range	10.0 to 100.0 N	:	5.0 N/Cm	In the range	100.0 to 160.0 N	:	10.0 N/Cm												
In the range	0.5 to 10 N	:	1.0 N/Cm																							
In the range	10.0 to 100.0 N	:	5.0 N/Cm																							
In the range	100.0 to 160.0 N	:	10.0 N/Cm																							
4.	Dimensions	<table> <tbody> <tr> <td>Instrument ></td> <td>Base Length</td> <td>:</td> <td>230 mm</td> </tr> <tr> <td></td> <td>Base Width</td> <td>:</td> <td>150 mm</td> </tr> <tr> <td></td> <td>Total Height</td> <td>:</td> <td>200 mm</td> </tr> <tr> <td>Wooden box ></td> <td>Length</td> <td>:</td> <td>250 mm</td> </tr> <tr> <td></td> <td>Width</td> <td>:</td> <td>180 mm</td> </tr> <tr> <td></td> <td>Height</td> <td>:</td> <td>230 mm</td> </tr> </tbody> </table>	Instrument >	Base Length	:	230 mm		Base Width	:	150 mm		Total Height	:	200 mm	Wooden box >	Length	:	250 mm		Width	:	180 mm		Height	:	230 mm
Instrument >	Base Length	:	230 mm																							
	Base Width	:	150 mm																							
	Total Height	:	200 mm																							
Wooden box >	Length	:	250 mm																							
	Width	:	180 mm																							
	Height	:	230 mm																							
5.	Weight	2.2 kg (1 kg equipment + 1.2 kg Box)																								
6.	Construction materials:	<table> <tbody> <tr> <td>Base</td> <td>:</td> <td>Cast / Machined Aluminum</td> </tr> <tr> <td>Handle</td> <td>:</td> <td>Tube with Rubber Cover</td> </tr> <tr> <td>Tension Bar</td> <td>:</td> <td>Stainless Steel</td> </tr> <tr> <td>Dial Cage</td> <td>:</td> <td>Cast Iron - Galvanised</td> </tr> <tr> <td>All exteriors</td> <td>:</td> <td>Hammer Paint</td> </tr> </tbody> </table>	Base	:	Cast / Machined Aluminum	Handle	:	Tube with Rubber Cover	Tension Bar	:	Stainless Steel	Dial Cage	:	Cast Iron - Galvanised	All exteriors	:	Hammer Paint									
Base	:	Cast / Machined Aluminum																								
Handle	:	Tube with Rubber Cover																								
Tension Bar	:	Stainless Steel																								
Dial Cage	:	Cast Iron - Galvanised																								
All exteriors	:	Hammer Paint																								



Where to apply Tensiometer on Fabric



How to apply Tensiometer on Fabric



Guidelines for use of Hand Tensiometer :

- Open lock nut (1) before use.
- Set Maximum Hand pointer (5) to zero mark by turning the centre knob (4).
- Grip only handle (6) of the Tensiometer and use one hand.
- Ensure that hand does not touch the base .
- Press firmly but with normal hand pressure on wire / felt and note reading.
- Take atleast 3 readings and average them out.
- Always bring the maximum hand (5) to "0" position before reuse.
- Keep the tensiometer longitudinally(longer side of tensiometer) parallel to the run direction of the fabric, at a distance of about 50 cm from the roller. (see diagram – 'How' to apply tensiometer.)
- As far as possible, the tension should always be measured between the stretch and return roll and the Tensiometer should be kept about 30 cm inside from edge of cloth. (see diagram – 'Where' to apply Tensiometer)
- Tensiometer should be stored in wooden box whenever not in use. Ensure that the lock nut is duly replaced.